









FIG. 3












4/24

FIG. 11





6/24

FIG. 16.






FIG. 17.



7/24

FIG. 18.



8/24





FIG. 20.





9/24

FIG. 21.




FIG. 22.










FIG. 23.





11/24

FIG. 29




FIG. 30 is a cross-sectional view of a mechanical assembly. The assembly includes a central component 90, a base 100, and a housing 80. Various parts are labeled with numbers: 12/24, 3, 70, 91, 81, 47, 87, 104, 103, 71, 101, 83, 85, 40, 106, 105, 107, 44, 42, 86, 84, 82, and 10A.

13/24

FIG. 34.






FIG. 35.




15/24

FIG. 36.



16/24


FIG. 37.






17/24

FIG. 38.




18/24

FIG. 39.




19/24




20/24

FIG. 41.




21/24

FIG. 42.



22/24



23/24

FIG. 44a.





FIG. 44b.



24/24

FIG. 45.

